

GOVERNMENT OF TAMILNADU WATER RESOURCES DEPARTMENT MADURAI REGION, MADURAI

REHABILITATION OF THE LEFT OUT COMPONENTS IN THE TANKS IN HANUMANADHI SUB BASIN IN RATHAPURAM TAKUK OF TIRUNELVELI DISTRICT.

ESTIMATE Rs. 101.80

LAKHS

DETAILED PROJECT REPORT

Name of Circle: Tamirabarani Basin Circle, Tirunelveli

Name of Division: Kodayar Basin Division, Nagercoil.

REPORT TO ACCOMPANY THE DETAILED PROJECT REPORT FOR THE WORK OF REHABILITATION OF LEFT OUT COMPONENTS IN THE TANKS IN HANUMANADHI SUB BASIN IN RADHAPURAM TALUK OF TIRUNELVELI DISTRICT

The Government of Tamilnadu have accorded the administrative sanction for Rs.283.74 Crores Vide in G.O.Ms.No. 81/ Public works (WR1) Department dated: 09.03.2010 for implementing IAMWARM Project in 26 sub basins under Phase III. The Hanumanadhi sub basin is one among the above 26 sub basins for which an amount of Rs.1388.68 lakhs has been provided towards rehabilitation works comprising five packages. Accordingly the following works were carried out in this sub basin.

REHABILITATION WORKS TAKEN UP

This sub basin consists of 12 anicuts, 108 tanks and 148.97 km long supply channels. The following rehabilitation works were carried out under IAMWARM Project in 84 tanks and 8 anicuts.

- Strengthening the tank bund by using Machineries.
- Reconstruction of Collapsed Sluices
- Repairs to sluices
- Repairs to weirs
- Providing S.G. Shutter / Plug arrangements to Sluices, Head sluices, Scour vents etc..
- Fixing Boundary Stones in the tank bund and water spread area.
- Repairs to anicuts.

LEFT OUT COMPONENTS

Out of the 84 tanks already rehabilitated, certain components have been left out without rehabilitation in four tanks, since the package works were carried out according to the DPR and as per the estimate. But during the WRO officials visit in the Sub Basin it was emphasized the need of attending major important defects and elected WUA representatives also requested to carry out the left out components.

Hence, this estimate is prepared to carry out the left out components by utilising the overall savings amount available and based on the agreed actions in the wrap up meeting chaired by the Finance secretary on 17.09.2012, which was communicated in the Engineer in Chief WRD Letter No. Tech cell / 57252/WB Mission/ 2009/Dated: 05.10.2012 and also the World Bank Implementation support mission draft aide memoir.

PROJECT PROPOSALS:-

- Raising and strengthening the Tank Bund (Veesadikulam Tank, Karuppilankulam tank, Keeranerikulami Tank and Thandayarkulam Tank).
- 2. Lining of Irrigation channels.
- **3.** Repairs to Adankarkulam anicut.

PACKAGEWISE ABSTRACT

SI. No	Package No	Name of Work	Total amount including L.S. (Rs. in Lakhs)
1.	01/ IAMWARM /	Rehabilitation of Left Out components	101.80
	WRD / HMD / Left	in the anicut and tanks in	
	out Works / 2012 –	Hanumanadhi Sub Basin in	
	2013	Radhapuram Taluk of Tirunelveli	
		District.	
		TOTAL	101.80

Rehabilitation of Left Out components in the anicut and tanks in Hanumanadhi Sub Basin in Radhapuram Taluk of Tirunelveli District.

WRO COST TABLE

SI.No	Description of Work	Quantity	Amount in Lakhs	Remarks
I. Tank Comp	onent			
1	Strengthening of Tank bund	4080 Rm	59.61	
2	Lining of irrigation channel	180 m	7.39	
II. Non Tank	Component			
1	Improvements to Anicut	1 No	32.00	
	Sub total		99.00	
а	Provision for contingences, Advertisement charges, Photographic charges @ 2.50%		2.50	
b	Provision for Labour welfare fund @ 0.3%		0.30	
	Total for Lump sum Provision		2.80	
	Total		101.80	

PHYSICAL AND FINANCIAL PROGRAM

SI. No	Description	I Ye	ar	ΠY	ear	Total		
NO		Quantity	Amount in Lakhs	Quantity	Amount in Lakhs	Quantity	Amount in Lakhs	
1	Strengthening	4080 Rm	59.61	Nil	Nil	4080 Rm	59.61	
	of Tank bund							
2	Lining of	180 m	7.39	Nil	Nil	180 m	7.39	
	irrigation							
	channel							
3	Improvements	1 No	32.00	Nil	Nil	1 No	32.00	
	to Anicut							
4	LS provisions		2.80				2.80	
	Total		101.80		Nil		101.80	

STATEMENT - 1

Rehabilitation of Left Out works in Hanumanadhi Sub Basin

Abstract Showing the details of Rehabilitation works proposed

SI. No	Details	Tanks Nos	Anicut Nos	Supply Channel Nos	Remarks
1	Available infrastructure in sub Basin	108	12	148.97	
2	Rehabilitation taken up under IAMWARM Project	84	8	108.21	
	a) Infrastructure in which all the components are in good condition and does not require rehabilitation now	80	7	108.21	
	b) Infrastructure taken up under IAMWARM but certain components not taken up then, but require rehabilitation now	4	1	Nil	
3	Tanks not taken up for rehabilitation since 2005 under any other scheme				
	a) Infrastructure in which all the components are in good condition and does not require rehabilitation now	24	4	40.76	
	b) Infrastructures in which certain components not taken up since 2005 but require rehabilitation now				
4	Total No of infrastructures requiring rehabilitation now.	4	1	Nil	

- 1 Certified that the works are proposed in the selected IAMWARM Sub Basin
- 2 Certified that the Panchayat Union tanks are not considered in this project
- 3 Certified that for item 2 b the components of the infrastructures now proposed were not taken up under IAMWARM Project
- 4 For item No 3 Certified that the works are not executed under various scheme (Viz. NABARD, PART II Schemes etc.,) and IAMWARM since 2005.

STATEMENT II - A

Rehabilitation of Left out Tanks & Infrastructures in Hanumanadhi Sub Basin of IAMWARM Project Rehabilitation of Tank works

Name of Sub basin - Hanumanadhi Sub basin Amount in Lakhs

SI	Name of Tank	Tank Bund Improvements		Repairs to Sluice		Reconstruction of Sluice		Repairs to weirs		Reconstruction of weirs		Shutter renewal		Total
No		Length in M	Amount	No	Amount	No	Amount	No	Amount	No	Amount	No	Amount	Amount
1	Veesadikulam Tank,	770	8.24	-	-	-	-	-	-	-	-	-	-	8.24
2	Karuppilankulam tank,	830	9.93	-	-	-	-	-	-	-	-	-	-	9.93
3	Keeranerikulami Tank	950	9.67	-	-	-	-	-	-	-	-	-	-	9.67
4	Thandayarkulam Tank	1530	31.77	-	-	-	-	-	-	-	-	-	-	31.77
	Total	4080	59.61	-	-	-	-	-	-	-	-	-	-	59.61

STATEMENT II - B Rehabilitation of Irrigation Channels

Name of Sub basin - Hanumanadhi Sub basin

Amount in lakhs


SI No	Name of Tank	Desilting of Irrigation Channel		Lining of irrigation channel		Repairs to Drops, Syphon, Cistern		Repairs to culvert, aqueduct etc			Shutter renewal	Total Amount
		Length in M	Amount	No	Amount	No	Amount	No	Amount	No	Amount	
1	Veesadikulam Tank,	-	-	1(30M)	1.25	-	-	-	-	-	-	1.25
2	Karuppilankulam tank,	-	-	1 (30M)	1.25	-	-	-	-	-	-	1.25
3	Keeranerikulami Tank	-	-	3 (90M)	3.64	-	-	-	-	-	-	3.64
4	Thandayarkulam Tank	-	-	1 (30M)	1.25	-	-	-		-	-	1.25
	Total	-	-	6 (180M)	7.39	-	-	-	-	-	-	7.39

STATEMENT 11-C REHABILITATION OF ANICUTS AND SUPPLY CHANNEL

Name of Sub Basin : Hanumanadhi Sub

basin Amount in Lakhs

SI.	No Anicut/ Supply		Reconstruction of anicut		Repairs to Anicut		Repairs to Head Sluice		Forming flood bank		Shutter enewal	Supply Channel		Total
	Channel	No	Amount	No	Amount	No	Amount	No	Amoun t	No	Amount	Length in M	Amount	
1	Adangarkulam anicut	0	0	0	0	0	0	1	32.00	0	0	0	0	32.00
	Total	0	0	0	0	0	0	1	32.00	0	0	0	0	32.00



TN - IAMWARM PROJECT - PHASE - IV KOTTAKARAIYAR SUB BASIN

TYPICAL SKETCH FOR RAISING AND STRENGTHENING OF TANK BUND SCALE: NOT TO SCALE

Rehabilitation works for Left Out Infrastructure in IAMWARM Project in Hanumanadhi Sub Basin

GENERAL ABSTRACT

SL.No	TANK NAME / ANICUT	Total Amount in lakhs
ı	STRENGTHENING OF TANK BUND	
1	Vessadi kulam	8.24
2	Keeraneri kulam	9.67
3	Karruppilan kulam	9.93
4	Thandayar kulam	31.77
II	LINING OF IRRIGATION CHANNEL	7.39
III	ANICUT	
1	Aadangarkulam Anicut	32.00
	SUB TOTAL	99.00
	Labour Welfare Fund at 0.30%	0.30
	Provision for Photographic charges, Advertisement charges, Name board, Petty supervision charges, unforeseen items at 2.5%	2.50
	TOTAL	101.80

(Rupees One Crore, One Lakh and Eighty Thousand only)